



Original post set 1820 by Laughlin with witnesses: 10" beech N 31 W 7 links; 4" hornbeam S 83 E 15 links per Marion County Atlas pg. 5. No records of witnesses or monuments. 12-7-43 MCSO called 2" pipe was set. The pipe was badly split. Stake was in top of pipe 3" below roadway. Bolt was found at surface. Miller MCSO 6-24-75 called PK nail found. Wilcoxen 2-6-92 called square bolt. Excavated 4-7-94 and a square bolt found 10" down. A pipe and wooden hub were found 18" down. Harrison set. Re-tied 6-5-95 by Kiste.

14031802

REF,	DISTANCE	DECODIBITION	
NLT,		DESCRIPTION	
_1.	135.40'	SE corner of brick for ADDRESS 4850	
2.	115.60'	Mag nail w/brass washer S PwP#30-746 14"up	
3.	85.00'	PK nail S PwP#29-746 12"up	
4,	64.71	Top nut of fire hydrant	
5.	161.95	SE corner of birck for ADDRESS 4910	